

# Belt-Way Conveyor Belt Scales for Every Application

The **Belt-Way** 2 Channel I/O Option Board outputs production information to a P.L.C., Variable Frequency Drive, Chart Recorder, Scoreboard Display, or Printer.

## Low Speed Alarm / Speed Interlock:

Output P4.3 turns ON when your belt goes below a programmed speed. Use this output to alert the operator to belt problems (broken or slipping belt). The Speed Interlock function turns output P4.3 ON when the Belt goes OVER the programmed Speed. Use this output to turn on an Alarm to indicate conveyor is running, or start another device.

## Remote Clear Weight:

Use a Momentary Push-Button to ground input P4.4 to clear the accumulated weight total from a remote location.

## Remote Print:

Use a Momentary Push-Button to print a ticket from a remote location

## Analog Rate Output:

2 Independent Analog Outputs may be used in conjunction with a Chart Recorder, Variable Frequency Drive, or PLC to track production or control material flow.

## Digital Pulse Output:

May be connected to external counters or a PLC. Pulse width adjustable or True Quadrature Digital Pulse Output.

