

Touchscreen Remote Display

With Wireless Options

Real-Time Scale Data

Monitor one or multiple scales from your control room or dredge.

Enhanced Functionality

Reset totals or zero belts, one at a time, or simultaneously.

Wireless Options

Wireless connectivity is now more cost effective and reliable than ever. Users of portable crushing and screening equipment minimize tear down and setup time.

© * Å	
SCALE PRIMARY PRODUCT SHOTROCK	SET ZERO Belt must be running empty START
TOTAL TONS	3254.6
TONS / HOUR	134
METERS / MIN 188	LOAD % 47.5
MENU HELP Date: 11/01	1/2010 Time: 15:07 back on

On-Board USB Drive

Log production data, and alerts for one or multiple scales automatically to the on-board USB drive. Save screenshots for any display at any time.

